© Copyright 1998. Black Box Corporation. All rights reserved.

1000 Park Drive • Lawrence, PA 15055-1018 • 724-746-5500 • Fax 724-746-0746

BLACK BOX®
NETWORK SERVICES

AUGUST 1998
USB02

USB Expansion Port



CUSTOMER SUPPORT INFORMATION

Order **toll-free** in the U.S. 24 hours, 7 A.M. Monday to midnight Friday: **877-877-BBOX**
FREE technical support, 24 hours a day, 7 days a week: Call **724-746-5500** or fax **724-746-0746**
Mail order: **Black Box Corporation**, 1000 Park Drive, Lawrence, PA 15055-1018
Web site: **www.blackbox.com** • E-mail: **info@blackbox.com**

TRADEMARKS USED IN THIS MANUAL

Windows NT is a trademark, and Windows is a registered trademark of Microsoft Corporation.

Any other trademarks mentioned in this manual are acknowledged to be the property of the trademark owners.

Specifications

Cables — (2) 7-inch (17.8-cm) cables with 5-pin connectors

Bracket — Size: 0.75"H x 4.5"W (1.9 x 11.4 cm); Weight: 1.9 oz. (53.9 g)

Introduction

The USB Expansion Port lets you use two ports on one bracket, thus minimizing the amount of space used on your workstation. The Port is Windows® 95, Windows NT™, and Windows 98 driven, so additional software is not needed—just plug and play!

Installation

1. Unplug your computer.
2. Remove your computer's shell or cover.
3. Screw the bracket into an open slot on your computer.
4. Plug your bracket's 5-pin USB connector onto the USB pins provided on your computer's motherboard (see the top illustration on the next page).
5. Place your computer's shell or cover back on to your computer. The 2 exposed jacks are for "A" type USB connectors.(See the bottom illustration on the next page.)
6. Plug in your computer.
7. Turn on your computer. Installation is complete.